



測試報告/ Test Report

工服編號/ Application No 24-03-QAC-110

承辦日期/ Date of Receipt 2024/03/20

測試日期/ Date of Performance 2024/03/20~2024/03/27

報告日期/ Date of Issue 2024/03/27

委託機構/ Applicant 大谷興業有限公司

地址/ Address 台北市中山區長安東路 1 段 16 號 3 樓

樣品名稱/ Sample Description 大谷水性外部漆(SOWARD STAIN)各色

樣品型號/ Model No. ---

測試內容/ Report Content A. 樣品敘述與測試結果/ Sample Information & Results

B. 樣品圖片/ Sample Photo

C. 流程圖/ Flow Chart

1. 送測樣品及其相關訊息均由客戶提供並已經由客戶確認無誤。

Any sample(s) and its information listed in this document are provided and identified by clients.


2. 本報告僅對測試樣品負責。

This report only refers to the specimen(s); it does not imply the result of production to tested sample(s).

3. 非經本中心同意，本報告內容不得以任何方式摘錄複印使用。(全部複印除外)。

This Test Report cannot be reproduced, except in full, without prior written permission of the laboratory.

報告簽署人/ Approved by:



Laboratory Representative

The content of this PDF file is in accordance with its original issued Test Report. PDF files are for reference only.



A 樣品敘述/ Sample Information

No.1

樣品編號/ Sample No. 24-03-QAC-110

樣品名稱/ Sample Description 大谷水性外部漆(SOWARD STAIN)各色

樣品型號/ Model No. ---


測試結果/ Test Results

測試項目 Test Item(s)	儀器設備 Instruments	測試方法 Test Method	測試結果/ Test Results (單位/ Unit : ppm)	
			No.1	方法偵測極限 MDL
甲苯/ Toluene	GC-MS	Reference US EPA 8260D	N.D.	5.0
二甲苯/ Xylene	GC-MS	Reference US EPA 8260D	N.D.	5.0

備註/ Note :


1. N.D. : 即為偵測不到/ Not Detected.(低於方法偵測極限/ below Method Detection Limit.)
2. MDL : 方法偵測極限/ Method Detection Limit.
3. ppm : = mg/kg (0.1% = 1000 ppm)
4. 測試儀器中英文對照/ Sino-British Contrast of the instrument
 - a. GC-MS 氣相層析質譜儀
5. 測試人員/ Tested by : Andy
6. 檢閱人員/ Reviewed by : sujane

B. 樣品照片/ Sample Photo



測試部位：液體

C. 流程圖/ Flow Chart



Flow Chart of Extraction for Toluene/ Xylene

---報告結尾/ End of Report ---